Stantec Consulting Services Inc.20 Church Street – Suite 1710
Hartford CT 06103
Tel: (860) 948-1628 Fax: (860) 948-1629

stantec.com



Certification

May 17, 2012

Ms. Kimberley N. Tisa
PCB Coordinator/Environmental Scientist
Office of Site Remediation and Restoration
US EPA Region 1
1 Congress Street, Suite 1100 (CPT)
Boston, MA 02114-2023

Dear Ms. Tisa:

As required by 40 CFR Part 761 (a)(3)(D), Andrew Dixon (the property owner) and WEI North Haven Limited Partnership (the responsible party) are pleased to provide the following certification:

All sampling plans, sample collection procedures, sample preparation procedures, extraction procedures, and instrumental/chemical analysis procedures used to assess or characterize the PCB contamination at the cleanup site, are on file at:

Stantec Consulting Services, Inc. 100 Pearl Street, 11th Floor Hartford, Connecticut 06103

and are available for EPA inspection. All analytical methods used for site characterization meet EPA extraction and analytical methodologies.

The following parties certify that the foregoing is accurate and true on this 17th day of May, 2012.

Andrew Dixon
Property Owner

Date

Tel. 1) /11

WEI North Haven Limited Partnership Date

Responsible Party